



# Service Bulletin


Bulletin No.: 19-NA-230

Date: October, 2019

## INFORMATION

**Subject: Front Seat Side Airbag Label is Peeling, Falling Off or is Taped Back On**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EV	2017	2020			All	All

<b>Involved Region or Country</b>	United States, Canada, Mexico, Middle East
<b>Condition</b>	<p>Some customers may comment on a front seat side airbag label peeling off or is not displayed correctly.</p> 
<b>Cause</b>	The front seat airbag label is used for assembly purposes only and is supposed to be removed as per the PDI instructions.
<b>Correction</b>	DO NOT replace or tape the side airbag label back on the side seat airbag cover. Remove the airbag label and discard. Removing the label is included in the PDI cost and is not a warranty item.

5414809

Version	1
Modified	Released October 08, 2019

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION