



## 2008 – 2009 SportWagen



Volkswagen

Engine	Part	Part Number	Quantity
<b>2.0L TSI Turbo: CCTA, CBFA</b>	Oil Filter	06J-115-403-Q	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.6L (4.9qt)
	Drain Plug Gasket	See Tech Tip 17-12-02 Elsa Doc #2030603	1
	Pollen Filter (20K Only)	1K1-819-653-B	1
<b>Miscellaneous</b>	Air Filter	1K0-129-620-D	1
	Wiper Blade Set	1Q1998002	1
	Rear Wiper Blade	1K9955427	1

Engine	Part	Part Number	Quantity
<b>2.5L 5 Cylinder: CBTA,CBUA</b>	Oil Filter	06D-115-562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	6.0L (6.3qt)
	Drain Plug + Gasket	N-90813202	1
	Pollen Filter (20K Only)	1K1-819-653-B	1
<b>Miscellaneous</b>	Air Filter	07K-129-620	1
	Wiper Blade Set	1Q1998002	1
	Rear Wiper Blade	1K9955427	1

Engine	Part	Part Number	Quantity
<b>2.0L Turbo Diesel: CBEA</b>	Oil Filter	071115562C	1
	VW 507 00 Use synthetic oil SAE 5W-30	N/A	4.0L (4.2qt)
	Drain Plug Gasket	N-90813202	1
	Pollen Filter (20K Only)	1K1-819-653-B	1
	Fuel Filter (20K Only)	1K0127434A	1
<b>Miscellaneous</b>	Air Filter	1K0129620E	1
	Wiper Blade Set	1Q1998002	1
	Rear Wiper Blade	1K9955427	1



Volkswagen



## 2008 – 2009 SportWagen

2008-2009	Engine Code		Torque Spec
<i>Oil drain plug Torque</i>	2.0L	CCTA, CBFA	30 Nm
	2.5L	CBTA, CBUA	
	2.0L TDI	CBEA	
<i>Wheel hub bolt Torque</i>	2.0L	CCTA, CBFA	120 Nm
	2.5L	CBTA, CBUA	
	2.0L TDI	CBEA	

Revised 11/11/2019

### Resetting the service interval display

If the schedule maintenance service was not done by a Volkswagen dealer, the service interval display function must be reset as follows:

- With the ignition off, press and hold the **0.0** trip odometer reset button.
- Switch the ignition on. The service interval function is now in reset mode.
- Let go of the **0.0** button and, within 20 seconds, briefly press the **m** clock reset button
- After a short time, the screen switches back to the normal display. The reset mode is cancelled if the **m** button is not pressed within 20 seconds, or if the vehicle is driven before resetting is complete.



### Tips

- Do **not** reset the service interval function between scheduled maintenance intervals; doing so will result in an incorrect display.
- There are different instrument clusters for different models. Equipment and displays may vary.