

GPOP - Issue Review System

Part Number: 68043032A\$

Part Description: Speaker, Front Door

Issue Description: For a buzz squeak rattle (BSR) concern coming from the speaker area that cannot be recreated, the fastener in the armrest pull cup may not be fully torqued.

This fastener, if under torqued, causes the washer to spin and rattle. Please ensure this fastener is secured and washer is not spinning prior to speaker replacement.

~ _____ ~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking systems.