



# Technical Journal

TITLE:  
**Region Code Setting for 7" Media/DVD Player**

|  |  |  |                                   |
|--|--|--|-----------------------------------|
| <b>REF NO:</b><br>TJ 32593.1.1             | <b>ISSUING DEPARTMENT:</b><br>Technical Service          | <b>CAR MARKET:</b><br>United States and Canada |                                   |
| <b>PARTNER:</b><br>3 US 7510 Volvo Car USA |  | <b>ISSUE DATE:</b><br>2017-03-28               | <b>STATUS DATE:</b><br>2017-03-30 |
| <b>FUNC GROUP:</b><br>3900                 | <b>FUNC DESC:</b><br>Media, navigation and communication | Page 1 of 2                                    |                                   |

“Right first time in Time”

## Attachment

## Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|----------|-------|------|------|-------|------------|-------|---------------|------------------|
| 234  |     |          |       |      |      |       | 2017-9999  |       | -             | 201617-999952    |
| 235  |     |          |       |      |      |       | 2017-9999  |       | -             | 201617-999952    |
| 236  |     |          |       |      |      |       | 2017-9999  |       | -             | 201617-999952    |
| 256  |     |          |       |      |      |       | 2016-9999  |       | -             | 201505-999952    |

## CSC Customer Symptom Codes

| Code | Description   |
|------|---|
| XF   | Rear seat entertainment/No/reduced/incorrect function |

## VST Operation Number

## DTC Diagnostic Trouble Codes

Rows beginning with \* are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

## Text

**DESCRIPTION:**

After installing the 7" Media Player/DVD Player Rear Seat Entertainment (RSE) accessory, it may be necessary to set the DVD region code to US (region 1)

**SERVICE:**

To change the region code, use the RSE remote control to perform the following key sequence:

1. Press the up arrow
2. Press the down arrow
3. Press the up arrow again
4. Press the enter button

Select region code 1 (USA) and press Enter.

Test the DVD player using a US Region 1 DVD.

**VEHICLE REPORT:**

Only if the solution provided under Service has no effect. Use Concern Area "Vehicle Report/THD" and Sub Concern Area "Support Needed." Use Function Group 3900.