




# MPD UPDATE


## Electrical



<b>Solihull Built Vehicles with an Improperly Fitted Ground Point</b>		<b>16MY – 20MY RR Velar, F-Pace, RR Sport, Range Rover &amp; Discovery</b>
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> <li>Improperly fitted ground points lead to numerous customer symptoms early in the service life of the vehicle.</li> </ul> <p><u>Current Status:</u></p> <ul style="list-style-type: none"> <li>All market activities on harness and earth related issues are being captured in a cross-functional workstream between the UK Engineering and Product Investigation.</li> </ul> <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> <li>Please continue to submit EPQR's when you encounter a ground point or harness related issue.</li> </ul>		
<b>KPI's</b>		
Total VIN Count	Status	Issue Owner
		NAS: George Krzyzanowski

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

