

MPD UPDATE

Electrical



	<p>18MY – 19MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ.</p>
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - There are multiple issues in regards to the manufacturing process of the Image Processing Module A from the supplier Bosch, or the Central Configuration learn in. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Permanent Corrective Action (PCA) has been launched on Nov 6th 2019 with Pathfinder release 258. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Follow TOPIX Workshop manual 413-09 Warning Devices, Diagnosis and Testing - Follow DTC U3000-96 help text information. 	
KPI's	
Total VIN Count	Status
	<p>NAS: George Krzyzanowski</p>

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

