

MPD UPDATE

Electrical



<p>Pop Noise From Audio Output</p> <p>16MY – 20MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ equipped with InControl Touch Pro</p>	
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - Customer may state there is a pop noise or crackle when playing the audio. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - NGI 19B software was released in market on Sept. 18th 2019. - NGI 19C software will contain further system improvements. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Please raise a TA case if a vehicle is exhibiting this customer symptom with NGI 19B software. 	
<p>KPI's</p>	
Total VIN Count	Status
<p>NAS: George Krzyzanowski</p> <p>Issue Owner</p>	

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

