


# MPD UPDATE

## Electrical



<p><b>No Audio due to Audio Amplifier Module</b></p> <p><u>Problem Description:</u></p> <ul style="list-style-type: none"> <li>- Customer may state there is no audio present or volume control.</li> </ul> <p><u>Current Status:</u></p> <ul style="list-style-type: none"> <li>- Audio will be restored when the audio amplifier module is replaced.</li> <li>- Parts are being inspected by the supplier.</li> </ul> <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> <li>- Follow Pathfinder Audio guided flow path.</li> <li>- 18MY Range Rover, RR Sport &amp; Discovery follow LTB1226NAS2 to update to the AAM software</li> </ul>		<p>16MY – 20MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF &amp; XJ equipped with InControl Touch Pro</p> 
<b>KPI's</b>		
Total VIN Count	Status	Issue Owner
		NAS: Richard Conte

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

