



MPD UPDATE

Electrical - UPDATED



<p>No Start Due to GWM</p> <p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - Customer is able to unlock and lock the vehicle but not able to start vehicle. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Majority of vehicle software is available on diagnostic tool. - Awaiting 20MY MHEV software and 19MY Discovery. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Update prior to sale has been created for 19MY Range Rover, RR Sport & Discovery. - Updating the GWM will resolve this concern. All vehicle lines affected have a TOPIX point test updated with instructions to update the GWM software. 		<p>19MY – 20MY RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ</p> 
KPI's		
Total VIN Count	Status	Issue Owner
		NAS: Richard Conte

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

