

MPD UPDATE

Electrical



<p>Software Over The Air (SOTA) Does Not Complete First Time Through</p>		<p>16MY – 20MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ equipped with InControl Touch Pro</p>
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - SOTA download does not complete first time through <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Currently collecting known cases and developing a project. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Please submit an EPQR if you encounter this scenario. 		
<p>KPI's</p>		
Total VIN Count	Status	Issue Owner
		NAS: George Krzyzanowski

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

