




MPD UPDATE

Electrical



<p>Voice Control – Navigation Destination Entry</p> <p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - Voice control is not able to locate destination entry. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Ongoing investigation to further improve the voice control database. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Please report any customer complaint in regards to voice control via EPQR with information: <ul style="list-style-type: none"> - Recording of voice control input 		<p>16MY – 20MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ equipped with InControl Touch Pro</p> 
<p>KPI's</p>		
Total VIN Count	Status	Issue Owner
		NAS: George Krzyzanowski

 Solution Unavailable or project not yet accepted

 Solution known, not yet delivered

 Service Fix Available, Communication Published

