

MPD UPDATE

Electrical



<p>Web Browser Not Available</p> <p>16MY – 20MY RR Velar, RR Evoque, Discovery, Discovery Sport, RR Sport, Range Rover, F-Type, F-Pace, I-Pace, XE, XF & XJ equipped with InControl Touch Pro</p>	
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - Web Browser functionality is not available. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Ongoing investigation to release software to remedy this situation. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - In the interim please create a TA case as local Engineering is able to WebEx a fix to the vehicle. 	
<p>KPI's</p>	
<p>Total VIN Count</p>	<p>Status</p>
<p>NAS: George Krzyzanowski</p>	<p>Issue Owner</p>

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

