

**`Creep mode` maybe switched off after ignition cycle**

**19-20MY I-PACE**

**Customer Voice:**

- Creep Mode is switched off with each ignition cycle

**Technical Description:**

- After vehicles have been updated from NGI 18D to any version of 19A a software bug relation to creep mode has been introduced. This results in Creep mode switched off in the infotainment system and having to be subsequently switch on at the start of each drive cycle.

**Status:**

- Update the IMC to 19B

