

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 74604 - 2019 - 2020 MY Vehicles equipped with gasoline engine and Check Engine MIL with DTC P2402-00 stored

Models : Discovery / L462
Discovery Sport / L550
Evoque / L538
Evoque / L551
Range Rover / L405
Range Rover Sport /
L494
Range Rover Velar /
L560

Engineer Name : Priestner Matt

Last 01 NOV 2019 13:48:34

Modified :

Category : Driveability

Symptom : 698298 Malfunction Indicator Lamp

Content : Issue:
Engine MIL on.

Cause:
DMTL system DTC P2402-00 confirmed.

Repair Action:
Inspect the DMTL circuit for damage including pin fit and pin tension at connectors. If no root cause is identified, replace the full carbon canister assembly which includes the DMTL. Raise an EPQR so parts return can be organized.