



Preliminary Information

PIP5687 DTC P11CC NOx Sensor 1 Performance - Signal Low Set Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado MD 4500 5500 5600	2019	All	All	6.6L L5D	All

Involved Region or Country	North America
Condition	A vehicle may have a concern of the SES light on
Cause	The technician may find P11CC set alone

Correction:

If this is the first occurrence of this code being set with no other codes set, it may be caused by improper learning of the fuel system adaptation.

Please perform the Fuel System Adaptation Reset in GDS2.

If this is the second or higher occurrence, refer to SI diagnostics

This PI will be updated as information is received.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*4087248	Reset Fuel System Adaptation	0.2 HR
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	11/26/2019 - Created on



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.