



**** SOLUTION ****

Title Mack Chassis - **TerraPro (MRU) And Low Entry (LEU) Models** - Field Service Bulletin **FSB 381-042**, Warning Light Bar Replacement and Software Conversion Kit - **US07, US10, US10+OBD13, US14+OBD13 To US14+OBD16 Emissions, Model Years 2008 To 2017**

Mack Models

Mack Model LEU , MRU - TerraPro

Emission Standard

Emission Standard US10 , US10+OBD13 , US14+OBD13 , US14+OBD15 , US14+OBD16

Engine family

Engine family MP7 , MP8

**** SOLUTION ****

Cause Mack cabover models require a software conversion kit to be installed after a warning light bar replacement.

Solution Field Service Bulletin **FSB 381-042** is located under the Service tab in [Impact](#).

NOTE: Please make certain the latest P/N is being used.

Solution visibility **Dealer distribution**

Function(s)/component(s) affected

Function affected MID 140 – IC04 / IC05 , exterior lighting , dashboard/information display , FSB

Function Group

Function Group 381 combined instrument

Conditions

Vehicle operating mode when driving , when stationary

Administration

Author A241298

Dealer ID A241298

Last modified by RU4469V

Creation date 20-09-2018 20:09

Date of last update 26-11-2019 18:11

Review date 06-01-2020 00:01

Status Published

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.