



Technical Journal

TITLE:

Panorama roof panel, rattle noise when closing

REF NO: TJ 33624.4.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-11-14	STATUS DATE: 2019-11-18
FUNC GROUP: 8361	FUNC DESC: Lid	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2020		0000001-9999999	201835-201952
536							2019-2019		0000329-0069832	201746-201828

CSC Customer Symptom Codes

Code	Description
SC	Sun/moon/convertible roof/Hard/impossible to open/close
B2	Sun/moon/convertible roof/Squeak/rattle

VST Operation Number

VST Operation Number	Description
98710-2	Glass roof hatch adjust acc. TJ33624

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

* added vehicle type 224 (S60)

If rattle noise occurs from the panorama roof panel during closing (listen to the noise in attached service instruction), follow instruction under “Service”.

SERVICE:

Perform attached service instruction. Start with one side and test the opening and closing operation 10 times. If noise still occurs, perform the service instruction on the other side.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:
VST OP number: 98710-2

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 8361.