

NEW DIAGNOSTIC SOFTWARE AVAILABLE FOR DOWNLOAD



Notice Information

Ref	12666
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CAN) – November 13, 2019
12666-SVC

TOL Ref. #

New Diagnostic Software Available for Download

Diagnostic software version **2019-6** is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.

****No change to password (case sensitive): Moto219**

SUMMARY OF CHANGES:

1	New Software Functionality:	None
		New Model Launch:
		Daytona MOTO2™ 765
2	Engine ECM Calibrations:	<ul style="list-style-type: none"> • 030283-01 • 030284-01
3	Chassis ECM Calibrations:	None
		New Model Launch:
4	Instrument ECM Calibrations:	Daytona MOTO2™ 765
		<ul style="list-style-type: none"> • INST00085
5	Keyless ECM Calibrations:	None
6	New ECU Unlock Codes:	Daytona MOTO2™ 765 - 38423108
7	Calibration Description Corrections:	None
8	Bug Fix(es):	<p>A bug that was preventing the Autoscan 'Throttles Balanced' check from operating correctly on models fitted with Kehin KHE and KEN4 engine ECMs has been resolved.</p> <p>Access to the 'Adjust Throttle Balance function' has also been restored on affected models.</p>

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.

