

## NEW DIAGNOSTIC SOFTWARE AVAILABLE FOR DOWNLOAD



## Notice Information

Ref	12778
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

**TOL NOTICE (US&CAN) – November 25, 2019**  
**Ref. # 12778-SVC**

**TOL**

### New Diagnostic Software Available for Download

Diagnostic software version **2019-7** is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.

**\*\*No change to password (case sensitive): Moto219**

#### SUMMARY OF CHANGES:

1	<b>New Software Functionality:</b>	None
2	<b>Engine ECM Calibrations:</b>	<b>New Model Launch:</b>
		Rocket 3 GT
		<ul style="list-style-type: none"> <li>• 031012-01</li> <li>• 031013-01</li> <li>• 031017-01</li> </ul>
		Rocket 3 R
		<ul style="list-style-type: none"> <li>• 031018-01</li> <li>• 031019-01</li> <li>• 031020-01</li> <li>• 031022-01</li> <li>• 031023-01</li> </ul>
		Rocket 3 TFC
		<ul style="list-style-type: none"> <li>• 031024-01</li> <li>• 031025-01</li> <li>• 031029-01</li> </ul>

Multiple calibration updates for the following models when equipped with Triumph Shift Assist.

- Speed Triple S from VIN 867685
- Speed Triple RS,
- Tiger 1200 XRX
- Tiger 1200 XRX-LRH
- Tiger 1200 XRT
- Tiger 1200 XCX
- Tiger 1200 XCA

Updated Calibration for Street Triple RS – ABS from VIN 966534 (031043-03)

3 **Chassis ECM Calibrations:**

None

**New Model Launch:**

Rocket 3 GT

- INST00086
- INST00087

4 **Instrument ECM Calibrations:**

Rocket 3 R

- INST00088
- INST00089

Rocket 3 TFC

- INST00090
- INST00091

**New Model Launch:**

**Rocket 3 GT**

- IMM00029\_ROW
- IMM00030\_JP
- IMM00031\_US\_CA

**Rocket 3 R**

- IMM00032\_ROW
- IMM00033\_JP
- IMM00034\_US\_CA

**Rocket 3 TFC**

- IMM00035\_ROW
- IMM00036\_JP
- IMM00037\_US\_CA

5 **Keyless ECM Calibrations:**

**Updated Keyless ECM Calibrations (application software update):**

**Scrambler 1200 XC**

- IMM00023\_ROW
- IMM00024\_JP
- IMM00025\_US\_CA

**Scrambler 1200 XE**

- IMM00026\_ROW
- IMM00027\_JP
- IMM00028\_US\_CA

6 **New ECU Unlock Codes:** Rocket 3 GT, R and TFC:**83616126**

7 **Calibration Description Corrections:** None

**Bug 1 Description:**The 'Enter Company Details' screen is displayed every time the software is launched on some computers.

8 **Bug Fix(es):**  
**Fix:**A change has been made to the software installation process which should resolve this issue. For affected users, the 'Enter Company Details' screen should be displayed upon first launch of the software after installing the 2019-07 update. The screen should then not be displayed again.

Dealers and subsidiary managers are requested to provide feedback if this issue is still experienced after updating to 2019-07.

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.