

December 18, 2019

Version 3

## Buzzing or Whining When Adjusting Front Seat Forward and Backward

Supersedes 19-029, dated November 5, 2019, to revise the information highlighted in **yellow**.

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2013-19	Accord	ALL except LX	ALL
2018-19	Accord Hybrid		ALL
2014-15, 2017	Accord Hybrid	ALL	ALL
2014	Accord Plug-In Hybrid		ALL

### REVISION SUMMARY

This bulletin has been temporarily suspended; it will be revised and reposted in the future. If you did the repair indicated in this bulletin prior to **December 18, 2019**, make sure to use the warranty claim information provided below.

### WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
8511J5	Replace the driver's seat flex cable assembly.	0.5 hr	07409	04201	A19029A	81526-TVA-L11
8521J2	Replace the front passenger's seat flex cable assembly (includes weight sensor operation check).	0.6 hr	07409	04201	A19029B	81201-TBA-A61

Skill Level: Repair Technician

END

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.