

Technical Journal

TITLE:

No sound from front woofer speakers

REF NO: TJ 35330.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada		
3 US 7	PARTNER: 7510 Volvo Car USA	ISSUE DATE: 2019-12-02	STATUS DATE: 2019-12-06	
FUNC GROUP: 3953	FUNC DESC: Loudspeaker; loudspeaker cables	Page	1 of 3	

"Right first time in Time"

Attachment

File Name	File Size
TJ35330.jpg	0.1541 MB

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2020-2020		0049448-0050117	201946-201947

CSC Customer Symptom Codes

Code	Description		
FC	Audio other/Other audio problems		
XD	Audio other/Audio unit display does not work		
FX	Speakers/Muffled sound		
FY	Speakers/Distorted sound		
IB	Speakers/Does not work		

VST Operation Number

DTC Diagnostic Trouble Codes

Text

Technical Journal 35330.1.0



DESCRIPTION:

This TJ only concerns S60 cars with High Performance Audio (Base sound system) - Variant Attribute K502: <u>TJ35330.jpg</u>

If there is no sound coming from the front door woofer speakers, see advice under SERVICE.

SERVICE:

Perform a software upgrade in accordance with TJ 31543.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use warranty claim data as mentioned in TJ 31543.

VEHICLE REPORT:


Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3953.

To view TJ attachment continue to next page. This TJ has one attachment.

Page 2 of 3 2019-12-06



Technical Journal 35330.1.0



2019-12-06 Page 3 of 3