

Notice Information

| | |
|--------------|--|
| Ref | 13044 |
| Posted Date: | |
| Posted To: | General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin |
| Subject: | Service/Technical |

TOL NOTICE (US&CAN) – December 16, 2019
13044-SVC

TOL Ref. #

New Diagnostic Software Available for Download

Diagnostic software version **2019-8** is now available to download. Dealers should download this update from your Triumph Diagnostic Software page under the Service/Technical menu and begin using immediately.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure all bikes being serviced have the latest software downloaded.
- Please ensure all relevant staff are informed of this update.

****No change to password (case sensitive): Moto219**

SUMMARY OF CHANGES:

Launch of Bluetooth Connectivity Module Functionality

1 **New Software Functionality:**

- Connectivity Module Download
- Connectivity Module Diagnostics
- Enable/Disable Instrument connectivity menus

Automatic programming of the VIN to instruments when downloading Connectivity Module ready instrument calibrations.

2 **Engine ECM Calibrations:**

None

3 **Chassis ECM Calibrations:**

None

4 **Instrument ECM Calibrations:**

Connectivity Module Ready Instrument Calibrations:

Rocket 3 GT

- INST00086_CM
- INST00087_CM

Rocket 3 R

- INST00088_CM
- INST00089_CM

Rocket 3 TFC

- INST00090_CM
- INST00091_CM

Scrambler 1200 XC

- INST00092_CM
- INST00093_CM
- INST00094_CM

Scrambler 1200 XE

- INST00095_CM
- INST00096_CM
- INST00097_CM

Launch of Bluetooth Connectivity Module software

| | | |
|---|---|--|
| 5 | Connectivity Module Calibrations: | <ul style="list-style-type: none">• CM000001 |
| 6 | Keyless ECM Calibrations: | None |
| 7 | New ECU Unlock Codes: | None |
| 8 | Calibration Description Corrections: | None |
| 9 | Bug Fix(es): | None |

If you have any questions, please contact Triumph Customer Support at (888) 284-6288.