

Notice Information

Ref: 13139  
 Posted Date:  
 Posted To: General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin  
 Subject: Service/Technical

**TOL NOTICE (US&CAN) – December 20, 2019**  
**# 13139-SVC**

**TOL Ref.**

**Technical News 200**

Technical News 200 is now available for download on the Triumph Technical News library located at **Triumph Online > Service/Technical > Technical News** or you can consult the attached **Technical News 200** PDF. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

Technical News 200		
Item	Subject	Model Affected
200.1	Camshaft Cover Tightening Sequence	Tiger Sport, Speed Triple S, Speed Triple R, Speed Triple RS
200.2	Replacement Keyless ECM Setup Process	Scrambler 1200 XC and Scrambler 1200 XE
200.3	Pin Point Test - ABS Modulator Communication	Bonneville T100 from VIN 759204, Street Scrambler up to VIN 910740, Thruxton 1200, Thruxton 1200 R, Street Twin up to VIN 914973, Bonneville T120, Bonneville Bobber, Bonneville Bobber Black, Speedmaster from VIN 856224, Street Cup
200.4	Cylinder Head Oil Jet	Speed Triple S, Speed Triple R from VIN 735337, Speed Triple RS
200.5	Owners Handbook Correction - Instrument Functionality	Tiger 800 XR from VIN 855532
200.6	Keyless Ignition	Scrambler 1200 XC and Scrambler 1200 XE
200.7	Torque Change	Tiger Sport
200.8	Torque Change	Scrambler 1200 XC, Scrambler 1200 XE
200.9	Windscreen Fixings	Tiger 1200 XR, Tiger 1200 XRX, Tiger 1200 XRX-LRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA
200.10	Front Wheel Speed Sensor Routing	Speed Triple RS, Thruxton TFC

If you have any questions, contact your Regional Manager or call Triumph Customer Support at (888) 284-6288.

