

**\* \* TECHNICAL INFORMATION NOTICE \* \***

**DATE:** November 19, 2012

**TO:** Mitsubishi Motors Sales Managers  
Mitsubishi Motors Parts Managers  
Mitsubishi Motors Service Managers

**RE:** 2013 Outlander, Lancer and Lancer Sportback – Front License Plate  
Hardware Eliminated

**TIN NO.** TIN-12-42A-002


\*\*\*\*\*

**AFFECTED VEHICLES:** 2013 Outlander beginning December, 2012  
2013 Lancer/Lancer Sportback beginning September, 2012

**PURPOSE**

Affected vehicles are no longer being shipped with front license plate hardware (rubber nut and bolt package). Dealers are asked to use self-tapping screws for mounting the front license plate. License plates should be installed in the locations indicated by dimples in the front fascia. Dealers should use locally sourced, non-corroding, M6 fasteners, 15mm to 25 mm long. **Fasteners should be installed using hand tools only.**

**Please do not submit any claims for missing front license plate hardware.**



Rear license plate mounting screws will continue to be shipped in the glove box.