



INTEROFFICE MEMORANDUM

Original Publication Date: September 12, 2019

To: All Lexus Area General Managers / Assistant General Managers
From: Chuck Yaeger
Senior Manager, Lexus Fixed Operations

LIMITED SERVICE CAMPAIGN KLG (*Remedy Notice*)

**Multiple Models and Model Years
Safety Connect System - Vehicle Location Inaccurate**

Specific information for Area support is provided below.

Condition

The Data Communication Module (DCM) in the subject vehicles are equipped with software to identify the location of the vehicle using the Global Positioning System (GPS) to support features of the Safety Connect system. Due to incorrect programming in the DCM software, after November 2nd, 2019, the GPS coordinates for this system will be calculated incorrectly. This will cause the system to use incorrect vehicle coordinates if one of the system's features is activated.

Dealer Notification

The attached dealer letter will be sent to all Lexus dealers on September 12, 2019

DCM-12 or DCM-13/14 Re-Recalibration

During DCM-12 or DCM-13/14 recalibration, it is possible for the recalibration to fail. In the case of recalibration failure, the technician can re-recalibrate the DCM to the updated software type by performing some additional steps. Re-recalibration will require removing the DCM from the vehicle and the utilization of a specially provided cable to directly connect to the DCM. If a technician experiences a calibration failure, the Technical Instructions inform the technician to contact their Field Technical Specialist (FTS) for assistance. The FTS will be able to provide the following opcode for dealerships that experience this condition. This opcode should only be provided in cases where dealerships need to perform a re-recalibration on the DCM.

KL005	Confirm Calibration ID, Recalibrate DCM Type 12 or 13/14, calibration failure, then Re-Recalibrate DCM Due to Initial Recalibration Fail	5.6
-------	------------------------------------------------------------------------------------------------------------------------------------------	-----

Please reference the attached Dealer Letter for additional details.

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.