

WKF2 Workshop campaign - Replacing pulse sender

Version 2

English (US)



> Overview

> Parts required

> Ordering required parts

> Warranty processing

> Scope 1:

> Further information

English (US)



English (US)



English (US)



WKF2 Workshop campaign - Replacing pulse sender

Overview

Due to a manufacturing problem with the pulse sender for the crankshaft, there is a possibility that the engine will be difficult to start and as a result, engine power will be reduced on the affected vehicles.

If this happens, the warning message "Engine control fault" will be displayed in the instrument cluster. Furthermore, the "Auto Start/Stop" and "Adaptive cruise control (ACC)" functions will no longer be available.

To prevent this from happening, the pulse sender must be replaced on the affected vehicles.

Please arrange for this measure to be carried out on the affected vehicles the next time the vehicles arrive to the dealer.

Model type	911 (992)
Model year	2020
Number	2,406

Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
00004330452	Speed sensor	1 ea.	No

* The parts must be stored until such a time as the **related warranty or campaign claim has been credited** in WWS. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Ordering required parts

Parts will be automatically allocated to you at 95% of your dealer's assigned UIO. Additional parts may be ordered as needed, without PRMS ticket, once initial allocation has been exhausted.

Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1:

Damage code	WKF2 66 000 2
Working time	24 TU

Further information

Work instruction	TI No. 76/19, Group 2, Service, WKF2
Vehicle list and allocation	See attached
Technical Information*	See attached or refer to PCSS

* Please find enclosed the Technical Information in the form of a PDF file. Please bear in mind that this is provided for your information only. The version published in PCSS is the definitive version.

For further information, please contact:

Ryan Cooney

Regulatory Affairs

ryan.cooney@porsche.us

[992 2 76-19 WKF2 Replacing Pulse Sender.pdf](#)

307.7 KB

(166 views)

[WKF2 VIN List.xlsx](#)

54.9 KB

(54 views)

Created by [Ryan Cooney](#) on Jan 10, 2020 9:43 PM. Last modified by [Ryan Cooney](#) on Jan 10, 2020 10:17 PM.

Categories: Workshop Campaigns, 911 Carrera

Tags : [workshop](#), [year_k](#), [992 carrera](#), [wkf2](#)

1008 Views

[Report Abuse](#)

Content and Topics

Personal

Manage

Create

Your Groups >

Edit Profile >

Admin Console >

Discussion >

Your Content >

Change Password >

PPN Administration>

Files >

Your Places >

Document >

Collaboration >

Document

Blog Post >

Poll >

Message >

Event >

Photo Album >

Idea >

Space >

Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. [Legal notice](#). [Copyright](#). [Terms of use](#). [Privacy Policy](#). [Cookie Policy](#). [009](#)