

Range Rover & RR Sport MHEV Timing Chain	2019/2020 Range Rover & RR Sport equipped with AJ20P6
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> • Vehicle does not start <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> • There may be codes for camshaft position sensor stored in the PCM. Timing chain is found broken <p><u>Status:</u></p> <ul style="list-style-type: none"> • Under Investigation • Determine if the upper or lower timing chain failed • Verify the part numbers on the intake & exhaust VVTs • Take clear pictures of the timing chain • Raise a TA with all the aforementioned information included 	