

**FT4794 Missing p-clamps for engine power cables**

**Technical writer name**

**Nandan BS**

**Manual section**

**9**

| First Level Parts (100% of 25 vehicles) |             |     |
|---|-------------|-----|
| Material                                | Part Number | QTY |
| P-CLAMP ID 0.750"THK 0.030"M8           | N84090-05   | 2   |
| NUT LOCKNYL M6 YZ TRIV 96H C8           | N44887      | 1   |
| SCREW M6X20 H YZ TRIV 96H 8.8           | N40492      | 1   |

|                         |        |
|-------------------------|--------|
| <b>Nb hours Level 1</b> | 0.25 h |
|-------------------------|--------|

|            |           |
|------------|-----------|
| <b>MQR</b> | 7621-2015 |
|------------|-----------|

| Disposal of parts  |          |   |
|--------------------|----------|---|
| Removed parts are: |          | When the retained check box is check, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed, |
| Discarded          | Retained |   |
| -                  | -        |   |

| Client                        | Order | Road numbers |      | VIN           |               | QTY | Lang. | Customer | Target market | Plant | Config moteur | Model | NR | R1 |
|-------------------------------|-------|--------------|------|---------------|---------------|-----|-------|----------|---------------|-------|---------------|-------|----|----|
| Buffalo New York - NFTA       | LC12  | 1901         | 1923 | L82K6K9777345 | L82K8K9777377 | 23  | E     | -        | US            | PLB   | TD            | 40    | X  |    |
| Calgary Transit Alberta - CNG | LC69  | 8395         | 8396 | L82K2K9777388 | L82K4K9777389 | 2   | E     | -        | CA            | PLB   | TD            | 40    | X  |    |