

## Solution K92543202 Thursday, February 6, 2020 10:00:15 PM CET

## \*\* SOLUTION \*\*

Title	Volvo Chassis - Performance Bonus OBD13 And Newer
Volvo Models	volvo Chassis - Ferformance Bonus OBD15 And Newer
Volvo Model	VN2, VNL, VNM, VNX, VAH, VHD
Emission Standard	
Emission Standard	US10+OBD13, US14, US14+OBD15, US14+OBD16, US17
Engine family	
Engine family	11L Engine, 13L Engine, 16L Engine
** SOLUTION **	
Cause	Since the Start Of Production (SOP) 2013 there have been complaints about the Performance Bonus feature not working.
	With changes to the trucks electrical architecture and the way performance bonus is set up by the customers and dealers they are having trouble getting the functionality set properly.
	The Instrument Cluster (IC) also displays the target Fuel Economy value incorrectly giving the driver the impression that the function is not working.
Solution	<u>Click</u> here for more information on how to correctly set up and use the Performance Bonus feature on OBD13 and newer Volvo chassis.
	<b>NOTE:</b> Engine ECU software must be updated to the lastest level.
Solution visibility	Dealer distribution
Support Area	Americas, CBR, Warranty Support, Customer Uptime Support
Function(s)/compone	ent(s) affected
Function affected	1 1 0 EMS
Function Group	
Function Group	20 general
Customer effect	
Main customer effect	road behaviour, calibration/programming/pairing/missing operation, efficiency /abnormal behavior
Conditions	
Vehicle operating mode	when driving
Administration	
	ut9268h

A241298
31-10-2016 18:10
09-01-2020 15:01
31-01-2017 00:01
Published
GTT

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.