

Solution K42667415 Thursday, February 6, 2020 10:02:24 PM CET

** SOLUTION **

** SOLUTION **	
Title	Volvo Chassis - Diagnostic Trouble Code (DTC) SA 0 FMI 0 or SPN 0 FMI 0 Present On Fault Code Readout - US10 And Newer Emissions, Model Year 2011 And Newer
Volvo Models	
Volvo Model	VN, VNL, VNM, VNR, VNX, VAH, VHD
** SOLUTION **	
Cause	Tech Tool reports fault code SA 0 FMI 0 or SPN 0 FMI 0 in DTC (Diagnostic Trouble Code) list.
Solution	DTC SA 0 FMI 0 is caused by an aftermarket device installed on the datalink. Removal of this device and refreshing Tech Tool will render this code inactive or remove it outright. The device may be a hidden GPS tracking device, datalink analyzer, fuel management system, or electronic logs. If the device cannot be located, contact the owner or fleet for assistance.
Solution visibility	Dealer distribution
Function(s)/compon	nent(s) affected
Function affected	1 1 0 EMS, 2 1 0 ACM, 3 1 0 TECU, MID 128 – EMS, MID 130 – TECU, MID 144 – VECU, MID 223 – GSECU / GLGW, MID 233 – UDS, Diagnostic tool, CAN BUS J1939 / BACKBONE 1
Function Group	
Function Group	2841 Electronic Control Unit, 357 lighting control system, 368 control unit for functions concerning comfort and safety in drivers/passenger compartment, 381 combined instrument, 432 gear lever carrier, gear selector controls, 593 anti-lock brake (anti-skid)
Customer effect	
Main customer effect	calibration/programming/pairing/missing operation , diagnostics/methodology , efficien cy/abnormal behavior
Administration	
Author	a175606
Last modified by	RU4469V
Creation date	17-03-2016 12:03
Date of last update	28-01-2020 17:01
Status	Published

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.