

Subject

**Rattle Noise from Engine Found During PDS**

Market

**USA**

Service Category

**Engine/Hybrid System**

Section

**Engine Mechanical**

Applicability

**2020 RAV4 HV**

**APPLICABLE VEHICLES**

2020

RAV4 HV

**CONDITION**

Some 2020 model year RAV4 HV vehicles may exhibit a rattle noise from the upper engine valve/timing cover area when running.

Sample Sound Recording File



A25A-FXS Rattle Noise.wmv

**RECOMMENDATIONS**

If a vehicle is identified with this condition, please contact TAS or your FTS for further assistance.

If it's a Sunday or holiday, continue with diagnosis and repair, save all parts and details, contact TAS on the next available work day and review details with TAS engineer.

**LINK REFERENCES**

This Tech Tip does not contain any link references