

## Do Not Adjust the MOST Connector Pins!

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2018-2020	Odyssey	ALL	ALL
2019-2020	Passport	ALL	ALL
2019-2020	Pilot	ALL	ALL

There was a provisional procedure provided to all field engineers to attempt the repair of certain customers' vehicles that might have experienced issues related to the MOST connectors, resulting in the audio system shutting down and the speakers making popping noises.

This provisional procedure was done as a test to confirm the repair reliability before releasing an official repair to dealers. Our findings from the test concluded that the provisional procedure was **not** effective.

If this procedure was shared with you (dealer), please refrain from making any adjustment/repairs to the MOST connector pins. We are quickly working to provide a reliable repair and will release an official repair procedure once it is available.