

Latest Vehicle Concern Fixes



PHEV Stops Charging at 99%	20MY Range Rover & RR Sport PHEV
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Vehicle never charges past 99% <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• When at high SOC the VSC requests less than 500W. At this point the BCCM switches off the charging request and in some cases will not resume charging. <p><u>Status:</u></p> <ul style="list-style-type: none">• This will not affect normal drivability of the vehicle nor cause a MIL.• Please address any HV System related DTCs that may disrupt the charging system.• If no other root cause is found, software is in development and expected to be available in Q2 of 2020	

