

Technical Service Bulletin

			No:	TSB-13-11-004
			DATE:	April, 2013
			MODEL: See Below	
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER		[X] TECHNICIAN
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[] WARRANTY PROCESSOR		[] SALES MANAGER

PURPOSE

The timing chain upper guide was eliminated from certain vehicles beginning October 1, 2009 with 4B11 (Non-turbo or Turbo-charged) and 4B12 engines. This TSB provides updated service manual information.

NOTE: This change affects service parts for 4B1 series engines (2008–10 model years). Replacement engine blocks will not have attachment holes for these parts.

AFFECTED VEHICLES

2010 Lancer built from October, 2009 2010 Lancer Sportback built from October, 2009 2010 Lancer Evolution built from October, 2009 2010 Outlander with 2.4L engine built from October, 2009

AFFECTED SERVICE MANUALS

2010 Lancer Service Manual – Engine:

Group 11A Engine Mechanical [2.0L Engine Non-turbo] > Timing Chain > Removal and Installation

Group 11C Engine Mechanical [2.0L Engine Turbo] > Timing Chain > Removal and Installation

Group 11E Engine Mechanical [2.4L Engine] > Timing Chain > Removal and Installation

2010 Lancer Sportback Service Manual - Engine:

Group 11A Engine Mechanical [2.0L Engine] > Timing Chain > Removal and Installation

Group 11C Engine Mechanical [2.4L Engine] > Timing Chain > Removal and Installation

2010 Lancer Evolution Service Manual - Engine:

Group 11A Engine Mechanical > Timing Chain > Removal and Installation

2010 Outlander Service Manual - Engine:

Group 11A Engine Mechanical [2.4L Engine] > Timing Chain > Removal and Installation

The information contained in this bulletin is subject to change. For the latest version of this document, go to the Mitsubishi Dealer Link, MEDIC, or the Mitsubishi Service Information website (www.mitsubishitechinfo.com).

Replace the timing chain Removal and Installation procedure with the following information:

REMOVAL AND INSTALLATION

