



Pop Noise From Audio Output

2016 – 2020MY E-Pace, F-Pace, I-Pace, F-Type, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery & Discovery Sport equipped with InControl Touch Pro

Customer Voice:

- Popping sound or crackling noise from the audio system while in use.

Technical Description:

- IMC module clipping sound due to large processing functions.

Status:

- IMC Software 20A contains additional improvements and was released on March 9, 2020 via TOPIx.
- 20A is a SOTA only update.
- If you should encounter a further complaint after 20A software has been installed, please submit a TA case for guidance.

