



JaguarDrive Switchpack (ATCM) Inoperative

19 - 20MY I-PACE

Customer Voice:

- A customer may report that the All Surface Progress Control (ASPC) Dynamic Stability Control (DSC), driving mode and air suspension (if equipped) switches are inoperative and related warning messages are displaced on the Instrument Panel Cluster (IPC).

Technical Description:

- This may be caused by a software error within the ATCM that causes the module to not communicate to the network.

Status:

- This affects only certain vehicles built with specific version number ATCMs.
- TSB JLRTB02036NAS1 is being published to provide diagnosis and repair guidance, please refer to this bulletin should a customer express a concern.

