SERVICE BULLETIN

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Dat

BT20-006 ITB20-009 March 18, 2020

Reference:

2019-2020 QX50; MOONROOF ASSEMBLY REPLACEMENT

APPLIED VEHICLES: 2019-2020 QX50 (J55)

IF YOU CONFIRM

Classification:

The moonroof assembly needs to be replaced for any reason

AND

The replacement moonroof part number is one of the following:

- 91205-5NA0A
- 91205-5NA0B
- 91205-5NA0C

ACTION

Apply flocking tape to the moonroof inner finishers per ITB20-008.

• Refer to **PARTS INFORMATION** on the last page of this bulletin for flocking tape.

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You MUST closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY	
Flocking tape	J-50397-8 (1)	(2)	

⁽¹⁾ J-50397-8 is part of the Squeak And Rattle Kit J-50397.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Install Tape To Moonroof Inner Finishers	(1)	BX7AAA	ZL	32	0.3

⁽¹⁾ Reference the electronic parts catalog and use the Inner Blind Assembly 91382-**** as the Primary Failed Part (PFP).

EXPENSE CODE

EXPENSE CODE	DESCRIPTION	Max amount
041	Supplies (Flocking Tape)	\$ 4.00

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 18, 2020	ITB20-009	Original bulletin published

2/2 ITB20-009

⁽²⁾ See **EXPENSE CODE** below. Do not bill out the complete roll of flocking tape for one repair.