

Subject		Market	
Front Brake Squeak at Parking Lot Speeds		USA	
Service Category	Section		
Brake	Brake (front)		
Applicability			
2019-2020 RAV4 2WD			

APPLICABLE VEHICLES

2019-2020

RAV4

CONDITION

Some 2019-2020 model year RAV4 2WD vehicles may exhibit a front brake squeak at low/parking lot speeds (< 10 MPH). This condition is more likely to occur after a cold soak.

RECOMMENDATIONS

Please confirm low speed brake noise, capture an audio sound file or video and open a TAS case. Videos should not be longer than 10 seconds and should be TIS supported file type (.mpg, .mpeg, .mp3, .mp4, .avi, .wmv, .wma).

If it is a Sunday or holiday, continue with diagnosis and repair, save videos, and contact TAS at the next available opportunity.

LINK REFERENCES

This Tech Tip does not contain any link references