



Service Bulletin


Bulletin No.: 20-NA-081


Date: April, 2020

INFORMATION

Subject: Surface Rust on Front Seat Bottom Frames

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Bolt EV	2017	2020			All	All

Involved Region or Country	North America, Middle East, South Korea
Condition	 <p style="text-align: right; font-size: small;">5552481</p>
Cause	Depending on the exposure of the vehicle to outside weather conditions, including salt in the air, surface rust can be found on the underside of the front seat cushion frames.
Correction	This is a cosmetic condition in an area that is not visible to the customer during typical vehicle use. Please do not replace the front seat frames for cosmetic corrosion in areas that are not visible to the customer during typical vehicle use.



5552478

Note: Areas that are considered “visible to the customer during typical vehicle use” can be seen while standing outside the vehicle, sitting in the vehicle, or during entry/exit like illustrated above. This includes, but is not necessarily limited to: seat tracks, adjuster handles, and visible portions of the adjuster linkages.

Parts Information

No parts are required for this repair.

Version	1
Modified	Released March 30, 2020

