

SSM 48744 - 2020 F-Super Duty - Turn Signals Flash Fast After Flat Bed Upfits - FDRS Application Investigation 2017-2020 Continental - Creak Type Noise When Opening/Closing Front Doors - Built On Or Before 10-Jan-2020

Some 2020 F-Super Duty vehicles may exhibit a condition where the turn signals flash faster after removal of the factory pick up box and tail lamps for flatbed installation. Engineering is working to implement a solution for this condition. Advise the customer that a solution through FDRS is expected to be available 27-Apr-2020. Dealers are asked to follow-up with their customers to schedule a service appointment once the solution becomes available. Monitor OASIS for updates.