

SSM 48777 - 2020 F-Super Duty - Turn Signals Flash Fast After Flat Bed Upfits - FDRS Application Complete

Some 2020 F-Super Duty vehicles may exhibit a condition where the turn signals flash fast after removal of the factory pick up box and tail lamps for flatbed installation. To prevent the turn signals from flashing fast, the BCM will need to be configured using the FDRS scan tool. Start a vehicle session in FDRS using the vehicles VIN and go to the toolbox tab. The BCM will have an application labeled Turn Signal Lamp Configuration. Download and run this application to configure the turn signals.