

# LATEST VEHICLE CONCERN FIXES

## POWERTRAIN



### Idle Surging After Timing Cover Removal

13-17 MY Discovery Sport, RR  
Evoque, XE, XF equipped with 2L  
GTDi engine

#### Customer Voice:

- The engine idle is surging following a previous repair.

#### Technical Description:

- The engine timing was set during a previous repair and the vehicle now exhibits a surging idle and/or P0505 stored.

#### Status:

- The mechanical timing of the engine needs to be confirmed as correct.
- TOPIx instructions must be completely adhered to.
- ALL tools outlined in the TOPIx work instructions must be used.
- Damaged tools must be repaired or replaced to complete the repairs properly.

