


LATEST VEHICLE CONCERN FIXES

ELECTRICAL



Pop Noise From Audio Output	2016 – 2020MY E-Pace, F-Pace, I-Pace, F-Type, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery & Discovery Sport equipped with InControl Touch Pro
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Popping sound or crackling noise from the audio system while in use. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• IMC module clipping sound due to large processing functions. <p><u>Status:</u></p> <ul style="list-style-type: none">• IMC Software 20A contains additional improvements and was released on March 9, 2020 via TOPIx and was suspended due to an issue loading map at PDI.• 20A1 is due to be released on April 14th via TOPIx.• If you should encounter a further complaint after 20A1 software has been installed, please submit a TA case for guidance.	 A close-up photograph of two circular car speakers. The speakers are mounted on a dark, textured surface, likely the interior of a vehicle. The top speaker is larger and has a prominent mesh grille. The bottom speaker is smaller and also has a mesh grille. The lighting is focused on the speakers, creating highlights and shadows.

