



Technical Service Bulletin

Technical Service Bulletin: TSB200034	Released Date: 20-Apr-2020
FC2976 on [REDACTED]	Applications

FC2976 on [REDACTED] Applications

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Information Only - OEM Related Matter Not Covered By Cummins® - Contact Appropriate OEM Dealer or OEM Representative For Additional Information

Contents

Product Affected

- ISL9 CM2350 L101 ([REDACTED] only)
- L9 CM2350 L123B ([REDACTED] only)

Issue

Symptom:

- Active or inactive FC2979 on [REDACTED] transit units.

Root Cause:

- The Aftertreatment DEF Dosing Unit overheats due to hot engine air around the Aftertreatment DEF Dosing Unit during vehicle operation.

Resolution

[REDACTED] has released a newly designed Aftertreatment DEF Dosing Unit cover assembly that insulates the Aftertreatment DEF Dosing Unit from hot engine air.

Service Instructions

Contact the original equipment manufacturer (OEM) [REDACTED] for repair instructions. Reference [REDACTED] Instruction to Service ITS58760.

Document History

Date	Details
2020-2-19	Module Created

Date	Details
2020-4-16	Added product affected.

Last Modified: 20-Apr-2020
