

CAMPAIGN LAUNCH STATUS

N456 – SERVICE ACTION 19-20 MY L405 & L494



SERVICE ACTION N456 – POWERTRAIN CALIBRATION ROBUSTNESS	
AFFECTED MODELS	2019-2020 MY RANGE ROVER RANGE ROVER SPORT I6 3.0L
VOLUME AFFECTED	21,768 USA
REPAIR	Affected vehicles require a software update to the Powertrain Control Module (PCM)
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	May 4th 2020
Notes	Complete at next service visit for sold cars

- Affected vehicles require a PCM calibration update to improve the system robustness to ensure in-use testing for emission compliance is maintained on I6 3.0L engines
- This campaign supersedes customer satisfaction campaign N418 for improved drivability.
- Approx. 7000 affected vehicles are in retailer unsold inventory. Please check BBSS for current list of unsold VIN by retailer.

