

STAR ONLINE PUBLICATION

Case Number: S2021000002

Release Date: 04/18/2020

Symptom/Vehicle Issue: Valve Body Pressure Testing Plug Inspection

Technician: OEM RFE valve body testing and or replacement, verify the required seven (7) Part #06030035 plugs are installed and torqued to 45 in-lb (5Nm).

Repair Procedure: See below required procedure.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found