

Classification:

EL15-012a

Reference:

ITB15-019a

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

May 13, 2020

CONFIGURATION FOR BLANK REPLACEMENT BCM

APPLIED VEHICLES: 2003 – 2006 G35 Sedan (V35) 2009 – 2013 G37 Convertible (V36)
 2007 – 2008 G35 Sedan (V36) 2014 – 2015 Q60 Convertible (V36)
 2009 – 2013 G37 Sedan (V36) 2003 – 2008 FX35/45 (S50)
 2011 – 2012 G25 Sedan (V36) 2006 – 2010 M35/45 (Y50)
 2003 – 2007 G35 Coupe (V35) 2015 Q40 (V36)
 2008 – 2013 G37 Coupe (V36)
 2014 – 2015 Q60 Coupe (V36)

This bulletin is no longer applicable.

Discard previous versions of ITB15-019.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 30, 2015	ITB15-019	Original bulletin published
May 13, 2020	ITB15-019a	Bulletin no longer applicable

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.