

Classification:

RA17-002a

Reference:

ITB17-047a

 COPYRIGHT© NISSAN NORTH AMERICA, INC.
 Date:

May 4, 2020

2017 QX60; WHEEL ALIGNMENT AND ICC SENSOR ADJUSTMENT SERVICE INFORMATION

APPLIED VEHICLES: 2017 QX60 (L50)
 2017 QX60 Hybrid (L50)

This bulletin is no longer applicable.

Discard previous versions of ITB17-047.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
August 10, 2017	ITB17-047	Original bulletin published
May 4, 2020	ITB17-047a	Bulletin no longer applicable

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.