



Service Bulletin

Bulletin No.: 20-NA-114

Date: June, 2020

INFORMATION

Subject: Information on False Setting of DTC U0212

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT4	2020	2020	—	—	All	All
	CT5						

Involved Region or Country	North America, China, Europe, Cadillac Korea (South Korea), Middle East
Additional Options (RPOs)	Vehicles equipped with STEERING COLUMN LOCK-ELECTRICAL (N06)
Condition	Technicians may find DTC U0212 set in the IPC, BCM or CGM.
Cause	The cause of the condition may be that DTC U0212 is a false reading that mapped incorrectly on vehicles equipped with RPO N06.
Correction	Technician is to ignore DTC U0212 setting and diagnose as DTC U0236.

Parts Information

No parts are normally required for this repair.

Version	1
Modified	Released May 26, 2020