



TO: All OEMs
FROM: Application Engineering
SUBJECT: Running Change to ACM Software for MY2020

SUMMARY

There is an upcoming running change (RC1) for ACM software that will be installed when OEMs or distributors program with DiagnosticLink®. The hardware part number for the ACM module will remain the same (**A 000 446 97 54**). OEMs are instructed to continue ordering the same ACM hardware part number.

The differences between e7.60.2.0 and e7.61.1.0 are related to a number of software improvements, most notably ATS sensor diagnostics.



Figure 1: ACM Hardware Identification Label

With the MY2020 RC1 release, the current software versions for NAFTA HDEP engine controllers will be:

For MY2019.5 or Newer (with Full Range Misfire)

- CPC4 – R44_00_000a
- MCM2.1 – m14.2.1.3
- ACM2.1 – e7.61.1.0

For MY2019 and earlier

CPC4 – R44_00_000a
MCM2.1 – m6.8.0.1
ACM2.1 – e7.61.1.0

ACCESS TO DETAILED INFORMATION

For any technical questions, please contact your assigned DETROIT Application Engineer.